



Audit for environmental liability after an industrial accident

Client: Consulting company

Service employed: Environmental compliance experts

Duration: 2018

Environmental liability is typically an issue after an industrial accident. In this case we were appointed to assess the environmental liability after a large industrial accident (fire) in Greece on behalf of an insurance company.



During this assignment a methodology was constructed in order to acquire all the appropriate data. This methodology was divided into three stages: a) desktop study where all the files were reviewed, b) environmental audit during which the plant was visited, the key employees were interviewed and the environmental background of the area was determined, and c) technical reporting, during which all data were elaborated, the conclusions were drawn and the deliverable was written, reviewed and submitted to the client.

